



# Easy

Graphics Assisted Tolerance Reporting, Drag-n-Drop Graphical Report Creation, Cross Section & Free form Surface Scanning

## ◀ Graphics Assisted Tolerance Reporting

CMM-Manager


...highlights reporting and datum features for easy feature identification, and illustrates reporting dimensions and tolerances in the graphics window for easy visual confirmation.



## Drag-n-Drop Graphical Report Creation ▶

CMM-Manager

...provides drag-n-drop function for easy graphical report creation. The operator can simply drag a report item from the report database tree and drop it to the graphics report window, a graphics report table is created instantly.



## Cross Section & Free form Surface Scanning ▶

CMM-Manager

...allows the operator to easily define a cutting plane for cross section scanning or to pick a free form surface for digitization.

